



Driver Pre-Trip/Post-Trip Inspection Checklist

Driver Pre-Trip/Post-Trip Inspection Checklist

Vehicle (Make/Model/ Year): Mack/CXU613/2011	Hubometer Reading: 35000
Odometer Reading: 285352	Inspection Date: 09/16/2019
Trailer Number: 28	Time: 10:00

Check any item that needs attention. Provide details under Comments.

Tires

- Proper inflation
- Adequate tread
- Spare inflated
- Temperature

Lighting System

- Headlights
- Brake lights
- Turn signals
- Hazard lights
- Reflectors

Leaks (look underneath)

- Oil
- Fuel tanks

Safety Equipment

- Fire extinguisher
- Reflective triangles/flares
- Spare bulbs/fuses
- Emergency contact info
- Cell phone/two-way radio

Gauges

- Fuel
- Temperature
- Dashboard warning light

Trailers

- Brake connections
- Coupling chains
- Coupling king pin
- Doors
- Landing gear
- Tires/wheels

Other Equipment

- Windshield wipers
- Fans and defroster
- Brake system
- Mirrors
- Horn
- Exhaust system
- Seat belts

Comments:

Spare tire replaced, Fire Extinguisher Refilled, Emergency Contact Info Updated.

Mechanic's Signature

- Condition of vehicle is acceptable
- Defects noted above have been repaired
- Defects noted need not be repaired for safe operation of vehicle

Mechanic's Name

Steven

Date

09/16/2019

Mechanic's Signature



Driver Pre-Trip/Post-Trip Inspection Checklist

Driver's Signature

Driver's Name

Jake

Date

09/16/2019

Driver's Signature

A stylized, handwritten signature in black ink, appearing to read 'Jake'.