

Basic Information

Inspected By	Make
Steven	Ford
Date Completed	Model
09/16/2019	Focus
Technician	Unit #
Matt	12345

Image 1

Image 2

Image 3

Inspection Items

Inspection Items	Ok	N/A	Fail	Photo	Comments/Notes
Safety devices	\checkmark				Passed!
Structural and other critical components present and all associated fasteners and pins in place					Passed!
Operating and emergency controls					Passed!
Fluid levels checked (hydraulic oil, engine oil, fuel etc)					Passed!
Hydraulic power unit, reservoir, hoses, fittings, cylinders, and manifolds					Passed!
Electrical components, wiring harness, and electrical cables					Passed!
Loose or missing parts					Passed!
Tires and wheels					Passed!
Placards, warnings, and control markings					Passed!
Operator's manual legible and stored inside container located on platform					Passed!
Outriggers, stabilizers and other structures					Passed!
Guardrail system					Passed!
Dents or damage to machine					Passed!
Cracks in welds or structural components					Passed!
Battery water level	✓				Passed!

Add your logo

Quality Control Inspection Checklist

Inspection Items	Ok	N/A	Fail	Photo	Comments/Notes
Machine cleanliness/	\checkmark				Passed!
appearance					

Signature

Signature:

m

Date: 09/16/2019 f 🗲 in