



JSA #
184848

Job Safety Analysis

Job Site Information

Jobsite #

11087

Jobsite Address (street, city, state, & zip code)

Evacuation Point Assembly Area

First Aid Kits Location

JSA Conducted By

Thor Odinson

Operator Site Contact

Bob Goodman

Spanish Translator

Date

10/15/2020

Time

07:13 AM

Safety Officer(s) Contact Information

Inspector Signature

Jobsite Location

Job Site Information (cont.)

PPE Required

- ☒ Hard Hat
- ☐ Mask
- ☒ Steel Toes
- ☒ Safety Glasses
- ☒ Gloves
- ☐ Respirator
- ☐ FRC
- ☒ Ear Plugs
- ☐ FaceShield
- ☐ Traffic Vest
- ☐ Harnesses
- ☐ Others

Work Permits Completed and Signed?

Yes

Entry Permits Completed and Signed?

Yes

Hot Work Permit

N/A

Lock Out Tag Out

Yes

Permit #

66885

One Call 811

specify 811 number

Expiration Date

10/18/2022

Electrical

Yes

Gas

No

Water

No

Communications




Job Safety Analysis

JSA #
184848

N/A

No

Hazards

Potential Hazards	Task	Risk Rating	Control Type	Hazard Image(s)
Electrical (Fire)	Adding insulation Preparing site	L	PPE Engineering Controls Administrative Controls Wear correct gloves Make sure wire is not live	

Hazard Risk Rating	E - Extremely High	H- High	M - Medium	L - Low
Total Reported	0	0	0	0